

59-1
827.8






FIG. 1

09061084.041598






FIG. 4




FIG. 7




FIG. 8




FIG. 5




FIG. 6

00051084-044588




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 19




FIG. 14




FIG. 15





FIG. 16



2025-10-10 15:05:00




FIG. 17








FIG. 18

FIG. 20





65740-48079060




FIG. 25





FIG. 26



09051084 04500

FIG. 27




FIG. 28




FIG. 29




FIG. 30




FIG. 31




FIG. 32




FIG. 33




FIG. 34




FIG. 35





FIG. 36



+




FIG. 38





FIG. 39

FIG. 40




FIG. 41














FIG. 42



+







09061084-041598 FIG. 51





FIG. 52

09061084, 041593



09061034, 041598

FIG. 53





FIG. 54

09051084, 041593

09061084-041598

FIG. 55a.






FIG. 55b.







FIG. 55c 1084, 041598


FIG. 55d.

09061084 - 041 FEB 16 56a



05061034-746956b





F16.57

09061084.041598




FIG. 58

09061084, 041598




FIG. 59

09061084.041598







FIG. 60a.

09061084 F16 5606



09061084 041548
F16. 60c






928

929

09061084-041598

F16.60d


09061034 1341593
F16. 61a



— 700

904

902



907

906

09061084-041598
FIG. 61b





FIG. 62a.

902

900 →

09061034 041598

FIG. 626.







FIG. 63a


09061084, 041598

0906108451616300



09061084, 041598

Fig. 64



09061084, 041598





Fig. 65






FIG. 67

09061084-041598

09061084 "041598




FIG. 68




Fig. 70




Fig. 71

09061084, 041598

09061084-041598




Fig. 72

855T40" 480T9060




Fig. 73






FIG. 74

09061084-041593



09061084.041593

Fig. 75



1700~

Fig. 76

09061084.041598






FIG. 77
09061084.041598

09061084, 041598


F16.78






09061084-041598
F16.79


FIG. 8D
09061684, 04.15.98



1516.87-04.1593



09061084, 041577
716 82



**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☐ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☒ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.